

# Confirmation Certificate



This vehicle has been checked with hpi - the industry's leading vehicle check specialist

<b>VRM held by hpi:</b>	HV69YTE	<b>Plate Transfer:</b>	Checked and Clear
<b>VIN held by hpi:</b>	(Disclosed) *****50	<b>Certificate Release Date:</b>	18/07/21
<b>Details held by hpi:</b>	BLACK SKODA KODIAQ SPORTLINE TDI SCR 4 Estate 7 Speed S-Auto 1968cc Diesel	<b>Dealer Details:</b>	0466248, PAS
<b>Engine Number:</b>	DFHA576879	<b>Dealer Reference:</b>	Not Provided
<b>Date First Registered in UK:</b>	30 09 2019	<b>Dealer Address:</b>	PAS MOTORS SWALLOW EAVES SILVER STREET WINTERINGHAM SCUNTHORPE DN159ND
<b>Number of Keepers:</b>	Two	<b>Date and Time Of Enquiry:</b>	18/07/2021 17:56:16
<b>DVLA/DVLENI Export marker:</b>	No	<b>Vehicle Registration Mark (VRM) Supplied:</b>	HV69YTE
<b>Previous Colour:</b>	None	<b>Vehicle Identification Number (VIN) Supplied:</b>	Not Supplied
<b>CO2 Rating:</b>	147	<b>Mileage Reading Supplied:</b>	11981
<b>VRM/VIN Match:</b>	Not Conducted		
<b>Security Watch:</b>	Checked and Clear		
<b>Stolen Vehicles:</b>	Checked and Clear		
<b>Outstanding Finance:</b>	Checked and Clear		
<b>Condition Alert:</b>	Checked and Clear		
<b>Condition Inspected:</b>	Checked and Clear		

Unique Reference Number: 2587980263

This certificate tells you whether this vehicle has been given the 'all clear' by hpi after a comprehensive search on the following registers:

#### VIN Match

Compares the Vehicle Registration Mark (VRM) against the Vehicle Identification Number (VIN), where your dealer has provided both, to try to detect a 'ringer' or 'clone', i.e. a stolen vehicle with a false identity.

#### Vehicle Identity

Does the vehicle match the description recorded by the DVLA? Details of all road registered vehicles are recorded at hpi and the hpi check reflects information recorded on the vehicle's official V5 document.

#### First Registration

hpi confirms the vehicle's first date of registration in the UK to help establish the true value of the vehicle.

#### Outstanding Finance

Over half of new cars are bought using finance agreements, making them the property of the finance company until the debt is cleared. hpi has over 75 million records on this register, against which this vehicle has been searched to highlight any outstanding debt.

#### Condition Alert

Has a car been 'written-off' by an insurance company following damage or theft? hpi registers 40,000 write-offs every month. Each hpi check searches over 14 million records to make sure the vehicle is not a total loss or now belongs to an insurer.

#### Condition Inspected

hpi has a unique register of former damaged 'write-offs' which have passed an inspection against a Thatcham approved standard to confirm the integrity of the repairs.

#### Stolen Vehicles

Any vehicle currently recorded by the police as stolen is highlighted in the search.

#### Security Watch

Some vehicles such as hire cars, are at special risk from fraud or theft. This register checks for vehicles that are flagged as 'at risk' and being offered for sale without the owner's consent.

#### Plate Transfer

Plate transfers are perfectly legal, but can be used to cover a dubious past. A hpi check will automatically pinpoint all plate transfers since April 1990 and make sure that none of the prior identities have anything to hide.

#### Mileage

The National Mileage Register (NMR), with over 200 million readings, can help reveal discrepancies in a vehicle's mileage history.

Speak to a member of our team about running your own hpi check. Call us on: **0845 300 8905**  
(Mon - Fri 8am to 6pm; Sat 8am to 5pm; Sun 10am to 5pm)

hpi checks are not transferable. The results shown above, for the VRM or VIN provided, were believed to be correct on the date and time they were supplied to the hpi subscriber whose name appears above. These details are very likely to change over time. To conduct your own hpi check, with a £30,000 guarantee (subject to terms and conditions), visit [www.hpicheck.com](http://www.hpicheck.com) or call **0845 300 8905**.

cap hpi, Capitol House, Bond Court, Leeds, LS1 5EJ  
**0845 300 8905** [www.cap-hpi.com](http://www.cap-hpi.com)

# hpi

FOR SMARTER ALTERNATIVE DECISIONS™

# MOT test certificate

① Vehicle identification number

**TMBMK7NS3K8077450**

② Registration number

**HV69YTE**

③ Country of registration

**GB**

Make and model

**SKODA KODIAQ**

⑤ Vehicle category

**M1**

④ Mileage

**12,327 miles**

**Pass**

⑥ Date of the test

**28.07.2021**

⑧ Expiry date

**27.07.2022**

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 28.06.2022.

⑨ Location of the test

**WINTERTON ROAD, WINTERINGHAM, SCUNTHORPE, DN15 9NF**

⑩ Testing organisation and inspector name

**3758BB MERE GARAGE  
S. TOWNEND**

MOT test number

**7688 2942 7603**

Check that this document is genuine by visiting [www.gov.uk/check-mot-history](http://www.gov.uk/check-mot-history)

If any of the details are not correct, please contact DVSA by email at [enquiries@dvsa.gov.uk](mailto:enquiries@dvsa.gov.uk) or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at [www.gov.uk/mot-reminder](http://www.gov.uk/mot-reminder) or by telephone on 0300 1239000.



Driver & Vehicle  
Standards  
Agency

Issuer signature

**DHC**<sup>®</sup>

TEST REPORT

=BATTERY TEST=

AGM FLAT PLATE

SOC: 12.58V

RATED: 688EN

MEASURED: 568EN

GOOD & RECHARGE

STATE OF HEALTH

■■■■■■■■□□ 83%

STATE OF CHARGE

■■■■■■■■□□ 78%

CLIENT:

TEST DATE:

2021/07/28

11:44:22

BY:

*[Signature]*

**DHC**<sup>®</sup>

TEST REPORT

=STARTER TEST=

CRANKING VOLTS

10.43V NORMAL

=CHARGING TEST=

NO LOAD:

MIN MAX

■■■■■■■■□□

LOAD:

MIN MAX

■■■■■■■■■■

LOAD OFF: 14.50V

LOAD ON: 14.64V

DIODE RIPPLE

RIPPLE DETECTED

0.14V NORMAL

CLIENT:

TEST DATE:

2021/07/28

11:45:41

BY:

*[Signature]*













	PAS Motors				Mere Garage						Notes	
	OK	Fault	Repaired	NA	OK	Fault	Repaired	NA	MOT	Printout		
111 Exhaust system condition	✓				✓							
112 Emissions control test (appended to MOT)	✓				✓					✓		
113 Universal joints, CV joints, & CV boots	✓				✓							
114 Tyre tread depth - report (mm)	✓				✓						OSF 4 NSF 4 OSR 6 NSR 6	
115 Normal tyre wear	✓											
116 Tyre pressures checked	✓											
117 Tyre pressure monitoring system re-set	✓											
118 Wheels undamaged (inner & outer)	✓				✓							
119 Wheel covers & centre caps	✓											
120 Rack & pinion, linkage & boots	✓				✓							
121 Control arms, bushings & ball joints	✓				✓							
122 Springs visual inspection	✓				✓							
123 Struts & shockers visual inspection	✓				✓							
124 Power steering pump noise	✓				✓						ELECTRIC RACK	
125 Brake calipers & wheel cylinders condition	✓				✓							
126 Brake pad condition front	✓				✓						10 (mm wear remaining)	
127 Brake pad condition rear	✓				✓						6 (mm wear remaining)	
128 Brake disc condition front	✓				✓							
129 Brake disc condition rear	✓				✓							
130 Brake lines, hoses & fittings	✓				✓							
131 Parking brake effective & good operation	✓				✓						ELECTRIC CALIPERS	
132 Master cylinder & booster visual condition	✓				✓							
133 Owners guide	✓											
134 Service book / History printout	✓											
135 MOT certificates	✓											
136 Keys & remotes X2	✓										NEW BATTERIES FITTED 26/7/21	
PAS												
I certify that all items have been visually inspected				(PAS MOTORS). Date 29/07/2021								
I certify that all items have been visually inspected				SOUTH COAST (Mere Garage). Date 28/7/21								

<p><b>BODYWORK / WINDOW GLASS / MIRRORS</b></p> <p>D = DENT                  S = SCRATCH                  CH = CHIP                  CR = CRACK                  W = WHEEL DAMAGE                  T = TREE SAP MARKS                  B = BIRD DROPPINGS MARK</p>	
<p><b>INTERIOR SEATS / CARPET / DASHBOARD / ROOF</b></p> <p>T = TEAR                  S = SCUFF / WEAR                  B = BROKEN                  BN = BURN                  M = MISSING</p>	
<p><b>COMMENTS / RECOMMENDATIONS</b></p> <p>Used cars will have aged related marks commensurate with their age &amp; mileage. We try to sell cars in best condition and use the guide above to highlight any defects / marks which we have seen. Please have a good look round the car to satisfy yourself that we havent missed anything.</p> <p>Please note that any covering in the car described as leather, wood, aluminium, carpet etc may not be 100% actual leather, wood, aluminium or carpet etc. PAS Motors make no representation that any upholstery covering which is described as leather, wood, aluminium or carpet etc in any advertisement is actual real leather, wood, aluminium, or carpet etc as they may contain other man made materials.</p>	
<p>I confirm that I have test driven and inspected the above vehicle and there are no apparent faults, other than those listed above on the five page check sheet.</p> <p>Customer Signature _____</p> <p>Customer Print Name _____ Date _____</p>	



# Pre Scan Vehicle System Report

## VEHICLE INFORMATION

VIN	TMBMK7NS3K8077450
MAKE	Skoda
YEAR	2019
MODEL	Kodiaq
ENGINE	2.0L TDI-CR (DFHA)
SYSTEM	CodeScan
LICENSE PLATE	HV69YTE
ODOMETER	12329 MI

## CODE SCAN RESULTS

### Systems Analyzed: 24

- ✔ 01-Engine Management: 0
- ✔ 02-Transmission: 0
- ✔ 03-Brake Electronics: 0
- ✔ 08-Airco: 0
- ✔ 09-Central Electronics: 0
- ✔ 13-Adaptive Cruise Control: 0
- ✔ 15-Airbag - SRS: 0
- ✔ 17-Instrument Cluster: 0
- ✔ 19-Diagnostic Data Interface-Gateway: 0
- ✔ 22-4WD Electronics: 0
- ✔ 36-Seat Memory Driver: 0
- ✔ 3C-Lane Change Assistant: 0
- ✔ 42-Door Electronics Driver: 0
- ✔ 44-Steering Assist (separated): 0
- ✔ 52-Door Electronics Passenger: 0
- ✔ 5F-Information Control Unit: 0
- ✔ 6C-Back Up Camera: 0
- ✔ 6D-Trunk Electronics: 0
- ✔ 76-Parking Help: 0
- ✔ 2B-Electronic Steering Column Lock: 0
- ✔ 75-Telematics Communication Unit: 0
- ✔ A5-Front Sensor Driver Assistance System: 0
- ✔ B7-Access/Start System Interface: 0
- ✔ CA-Control Module For Sunroof: 0
- ✔ OBDII Codes (\$03): 0
- ✔ OBDII Permanent Codes (\$0A): 0



**READINESS MONITORS**

**Tests Complete**

- Fuel System
- Comprehensive Component

**Not Complete**

- EGR/VVT
- NMHC Catalyst
- NOx Aftertreatment
- Boost Pressure System
- Exhaust Gas Sensor
- PM Filter





Service Invoice Details Division ID: DMK

Invoice Number: 92778	Invoice Date: 06/08/2021 15:15	Invoiced By: Sam Tate
Job Number: 91420	Vehicle: Skoda Kodiaq Sportline Tdi Scr 4	
VIN: TMBMK7NS3K8077450	Registration: HV69 YTE	Mileage: 12,351 Fleet Number:
Order Number:	Date In: 04/08/2021	Service Advisor: Michelle Puckering

Invoice To - GSCSH
PAS Motors Silver Street Winteringham Scunthorpe DN15 9ND

Customer
PAS Motors Silver Street Winteringham Scunthorpe DN15 9ND

Carry out 1st Variable - £259

Operations	Code	Value	*
Carried out 1st Variable		110.39	S

Part Number	Description	QTY	List	Value	*
03N115562B	FILTERELEM	1.00	10.46	10.46	S
N 90813202	SUMP PLUG	1.00	3.79	3.79	S
5Q0819669	OD. FILTER	1.00	25.46	25.46	S
G 052164M2	SCREEN WASH	1.00	5.39	5.39	S
WHT000729A	BOLT	3.00	1.33	3.99	S
GSS5545M9EURBAR	OEL 0W30	4.70	11.99	56.35	S

Requirement Subtotal **215.83**

Carried a visual vehicle health-check free of charge

Operations	Code	Value	*
Thank you for choosing D M Keith, we hope we were able to deliver a 5 star experience for you.		0.00	S

We have carried out a free vehicle health-check on your car and a complimentary wash & vac.  
 The Technician who worked on the car today was..  
 Craig Eastwood  
 The Advisor who looked after you was .. Sam Tate  
 Your next service is due in 10,000 miles or a year whichever is the sooner and your MOT is due on or before .. 30/09/2022

Thank you once again and please tell us if you have any comments, compliments or concerns about our service today.

Requirement Subtotal **0.00**

Invoice Total

Payment Method

* Tax Type	Rate %	Goods Value	Tax
------------	--------	-------------	-----



# Maintenance list



Order no. 91420	Sales model NS738Z	Registration number HV69YTE	Registration 2019-09-30
Vehicle identification number TMBMK7NS3K8077450	Engine code DFHA	Mileage/km 12349	Service advisor
Sales model KODIAQ AMB TD140/2.0A7A	Gearbox code TNY	Model year 2019	Date 06.08.2021

## Inspection with oil change (flexible)

When receiving the vehicle	OK / completed	Not OK	Rectified
Check connect services and activate workshop mode	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Vehicle interior	OK / completed	Not OK	Rectified
Service interval display: Reset	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn: check function.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Odour and allergy filter: Clean housing and renew filter element	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
③ Spare wheel: Check condition and wear pattern of tyre; enter tread depth <input type="text" value="3.8"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spare wheel tyre pressure: Check <input type="text" value="40"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Vehicle exterior	OK / completed	Not OK	Rectified
Front lights - check function: Side lights, dipped beam, main beam, fog lights, turn signals, hazard warning lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tail light cluster - check function: Brake lights (including high-level brake light), tail lights, reversing lights, rear fog light, number plate light, turn signals, hazard warning lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
③ Windscreen: Visual check for damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
③ Windscreen wiper blades: Check for damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Underside of vehicle	OK / completed	Not OK	Rectified
Engine oil: Drain or extract; renew oil filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ABS sensor cable: visual check for damage and correct position	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
③ Brake system: inspecting for leaks and damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## VEHICLE HEALTH CHECK

Customer PAS Motors  
 Telephone No 01724733451  
 Job Number 91420  
 Dealer Skoda Hull

Vehicle Skoda KODIAQ Sportline Tdi Scr 4  
 Reg No HV69 YTE  
 VIN TMBMK7NS3K8077450

Mileage 12351  
 Colour Black  
 Technician Craig Eastwood  
 Check Completed 06 Aug 2021 12:28

Underbonnet	Red	Amber	Green	Report & Recommendations	Hours
Engine Oil Level/Anti Freeze/Air Filter	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Brake Fluid	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Water/Oil/Fluid Leaks	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Alternator Belt/Battery	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Power Steering Fluid	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Timing Belt	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Fuel System/Fuel Filter	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Spark Plugs	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		

Brakes & Hubs	Red	Amber	Green	Report & Recommendations	Hours
Front Brakes	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Rear Brakes	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Wheel Bearings	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Hoses/Pipes/Cables	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		

Check Underside (vehic...	Red	Amber	Green	Report & Recommendations	Hours
Check exhaust system/catalyst and mountings	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Check condition of steering joints, gaitors, excess play	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Check suspension dampers for leaks and mountings secure	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Rear Suspension	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Driveshafts/Oil Leaks	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
Check front suspension	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		

Additional Items	Red	Amber	Green	Report & Recommendations	Hours
Additional Item	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		

Please note: This report is a visual inspection only. Further checks may be necessary to determine the full extent of requirements.



## Complete record

### Vehicle data

Vehicle identification number	TMBMK7NS3K807745D
Type designation	KODIAQ AMB TD140/2.0A7A
Date of delivery	2019-09-30

### Inspection with Oil change (flexible)

Date	2021-08-06
Mileage/km	12349 mi
Order number	91420
Additional work carried out	✓ Dust and pollen filter
Carried out by	D M Keith Ltd (Hull) BEVERLEY HIGH ROAD HU6 7AD HULL United Kingdom
Authorised SKODA service partner	Yes

### Delivery inspection

Date	2019-06-27
Mileage/km	0 mi
Order number	100107
Carried out by	SPARSHATTS OF BOTLEY Broad Oak SO31 2EU SOUTHAMPTON United Kingdom
Authorised SKODA service partner	Yes